






Speed Spout Manual
KICE DATA SHEET | SS-11




Series 10




Series 40



Series 50



Series 50/60



Series 70



Series 80



Series 90



Speed Spout Handles Material Efficiently...



Spouting floor in flour mill featuring a rotary stream splitter dividing product into four Speed Spout outlets.

Gravity spouting, positive pressure conveying, and Dust Duct control systems showing the versatility of Speed Spout components.

Speed Spout supplying finished product to gathering screw.



Speed Spout used in spouting and dust control on roll stands.

Top floor cyclone receivers incorporating Speed Spout fittings and Dust Duct manifold.



www.kice.com

We make your job easier. Today.

How to order Kice components

Kice QuikShip Center Hours:

Available Monday through Friday
7:30 AM to 5:00 PM CST

- ▶ Call us toll-free 1-877-289-5423
- ▶ Fax your order to 316-744-9649
- ▶ E-mail your order to quikship@kice.com
- ▶ Mail your order to: ATTN: QuikShip Center

Standard Ground Service Shipping Times from Wichita, KS



Stock items shipped same day if called in before 12:00 Noon

For NEW and current customers: We accept
Discover, MasterCard, Visa, and American Express



5500 N. Mill Heights Drive
Wichita, KS 67219 USA

Phone: 316-744-7151

Fax: 316-744-7355

e-mail: sales@kice.com

www.kice.com

QuikShip Center

Toll Free: 1-877-289-5423

e-mail: quikship@kice.com

Whether your system is a dream for the future or has been running for years - **we make your job easier.**



Kice Industries, Inc. / World Headquarters

